

THE CARBON VALLEY AREA **FREE**
Consumer Report
VOLUME 10 • ISSUE 8 • AUGUST 2010

***FFFPD Warns, Check
Smoke Detectors***

The Frederick-Firestone Fire Protection District responded to 8840 Silver Birch Blvd. in Frederick, Colorado. Responding units found a developing fire inside the structure. The fire was quickly attacked and extinguished approximately 30 minutes later by 18 firefighters. The 1 occupant inside the structure was able to evacuate before the arrival of the fire department. The occupant was treated on scene and transported to a local hospital with non-life threatening complaints.

The structure suffered moderate damage from the fire and extensive smoke damage but minimal water damage.

Frederick-Firestone Fire Protection District was assisted by staff from Mountain View Fire Protection District, Platteville-Gilcrest Fire Protection District and the Frederick and Firestone Police Departments.

These types of fires are a constant reminder to check the batteries and operation of your smoke detectors regularly.